**TASARAUTO GLOBAL SERVICES, S.L.**
C/ Puerto de Canencia 9 - 28729 (MADRID)
informacion@tasarauto.es
+34 918 412 771

| | |
|---|---|
| **IdEE** | 4937730 |
| **IdE** | 1803702 |
| **License plate** | MGS2446 |
| **VIN** | WAUZZZFY1P2067491 |
| **Model** | AUDI - Q5 - 40 TFSI 204 STRONIC QUATTRO |
| **Color** | |
| **Subclient** | 8899 |
| **Location** | 1989 |
| **Rate** | 4004 |
| **Price List** | 2 |
| **N° ADR** | |

| | |
|---|---|
| **Bodywork rate** | |
| **Mechanical rate** | |
| **Paint rate** | |
| **Spare parts discounts** | |
| **Material discount** | |
| **Km** | 78534 |
| **Fecha creación encargo** | 13/10/2025 |
| **Valuation Date** | 20/10/2025 |


| Element | Total |
|---|---|
| Bandeja trasera - Falta Falta | |
| Llanta aleacion Delantero Izquierdo - Forfait Smart repair | |
| Paragolpes delantero (Desmontado) - Pintura Leve | |
| Aletin delantero derecho - Pintura Leve | |
| Retrovisor Derecho - Sustituir Sustituir | |
| TAP - Pintura Leve | |
| total appraisal | 1,275.80 € |

**Tomas Generales**


Picture - 1


Picture - 2


Picture - 3


Picture - 4


Picture - 5


Picture - 6


Picture - 7


Picture - 8


Picture - 9


Picture - 10


Picture - 11



Picture - 12


Picture - 13



Picture - 14


Picture - 15

**Tomas Daños**


Picture - 16


Picture - 17



Picture - 18


Picture - 19


Picture - 20



Picture - 21


Picture - 22


Picture - 23



Picture - 24



Picture - 25



Picture - 26