TASARAUTO GLOBAL SERVICES, S.L.
C/ Puerto de Canencia 9 - 28729 (MADRID)
informacion@tasarauto.es
+34 918 412 771

IdEE	5843620
IdE	1634383
License plate	BB16OH
VIN	WAUZZZGB9PR059723
Model	AUDI - A1 - 25 TFSI 95
Color	
Subclient	8897
Location	1858
Rate	3004
Price List	2
N° ADR	

Bodywork rate	
Mechanical rate	
Paint rate	
Spare parts discounts	
Material discount	
Km	92099
Job creation date	01/09/2026
Valuation Date	02/09/2026

Element	Total
Paragolpes delantero (Desmontado) - Pintura Leve	
Aleta Delantero Izquierdo - Abollado Leve	
Carcasa de retrovisor Izquierdo - Pintura Leve	
Llanta acero Delantero Izquierdo - Forfait Smart repair	
Maneta Delantero Izquierdo - Pintura Leve	
Puerta Delantero Izquierdo - Pintura Leve	
Puerta Trasero Izquierdo - Pintura Leve	
Paragolpes trasero (desmontado) - Pintura Leve	
Aleta Trasero Derecho - Abollado Leve	
Puerta Trasero Derecho - Pintura Leve	
Bandeja trasera - Sustituir Sustituir	
TAP - Pintura Leve	
total appraisal	920.60 €

Tomas Generales



Picture - 1



Picture - 2



Picture - 3



Picture - 4




Picture - 5




Picture - 6



Picture - 7



Picture - 8




Picture - 9




Picture - 10



Picture - 11




Picture - 12




Picture - 13



Picture - 14



Picture - 15



Picture - 16


Tomas Daños



Picture - 17



Picture - 18



Picture - 19



Picture - 20



Picture - 21



Picture - 22



Picture - 23



Picture - 24



Picture - 25




Picture - 26



Picture - 27



Picture - 28




Picture - 29



Picture - 30



Picture - 31



Picture - 32



Picture - 33




Picture - 34



Picture - 35




Picture - 36



Picture - 37



Picture - 38



Picture - 39



Picture - 40



Picture - 41