

Id	1409039	M.O. Chapa	0.00
Matrícula	8176LPK	M.O. Mecánica	0.00
Bastidor	VSSZZZKJZMR150252	M.O. Pintura	0.00
Marca	SEAT	Desc. Recambios	0.00
Modelo	ARONA	Des. Material	0.00
SubModelo	1.0 TSI 110	Km	9461
Color			
Cliente	OK MOBILITY ESPAÑA SLU		
Ubicación	OK RENT A CAR CALONGE		
Tarifa	4 OK GROUP ES		
Nº de GFA			

Elemento	Acción	Nivel	REC	TP	TC	MP	Chapa	Pintura	Forfait	Total
Spoiler Delantero	Pintura	Leve	0.00	0.8	0.00	0	0.00	39.20	0	39.20 €
Carcasa de retrovisor Derecho	Pintura	Leve	0.00	0.3	0.00	0	0.00	14.70	0	14.70 €
Puerta Trasero Derecho	Pintura	Leve	0.00	0	0.00	80	0.00	80.00	0	80.00 €
Spoiler Paragolpes Trasero	Pintura	Leve	0.00	0.7	0.00	0	0.00	34.30	0	34.30 €
Paragolpes trasero (desmontado)	Pintura	Leve	0.00	0	0.60	80	21.00	80.00	0	101.00 €
Porton o maletero	Abollado	Leve	0.00	0	0.20	100	7.00	100.00	0	107.00 €
Paragolpes delantero (Desmontado)	Pintura	Leve	0.00	0	0.60	80	21.00	80.00	0	101.00 €
TAP	Pintura	Leve	0.00	0	0.00	45	0.00	45.00	0	45.00 €
Total tasación								522.20 €		

Imágenes



Imagen - 1



Imagen - 2



Imagen - 3



Imagen - 4



Imagen - 5



Imagen - 6



Imagen - 7



Imagen - 8



Imagen - 9



Imagen - 10



Imagen - 11



Imagen - 12



Imagen - 13



Imagen - 14



Imagen - 15



Imagen - 16



Imagen - 17



Imagen - 18



Imagen - 19



Imagen - 20



Imagen - 21



Imagen - 22



Imagen - 23



Imagen - 24



Imagen - 25



Imagen - 26



Imagen - 27



Imagen - 28



Imagen - 29



Imagen - 30



Imagen - 31



Imagen - 32



Imagen - 33



Imagen - 34



Imagen - 35



Imagen - 36



Imagen - 37



Imagen - 38



Imagen - 39



Imagen - 40



Imagen - 41



Imagen - 42



Imagen - 43



Imagen - 44



Imagen - 45



Imagen - 46



Imagen - 47



Imagen - 48



Imagen - 49



Imagen - 50