

Id	1351811	M.O. Chapa	0.00
Matrícula	7198LGM	M.O. Mecánica	0.00
Bastidor	VF7SXHNPLYLT542269	M.O. Pintura	0.00
Marca	CITROEN	Desc. Recambios	0.00
Modelo	C3	Des. Material	0.00
SubModelo	1.2 PURETECH 110 EAT6shine	Km	16326
Color			
Ciente	OK MOBILITY ESPAÑA SLU		
Ubicación	PENDIENTE DE ASIGNAR CAMPA		
Tarifa	4 OK GROUP ES		
Nº de GFA			

Elemento	Acción	Nivel	REC	TP	TC	MP	Chapa	Pintura	Forfait	Total
Alojamiento puerta Delantero Derecho	Pintura	Leve	0.00	0	0.00	80	0.00	80.00	0	80.00 €
Paragolpes trasero (desmontado)	Pintura	Leve	0.00	0	0.60	80	21.00	80.00	0	101.00 €
Puerta Delantero Izquierdo	Abollado	Leve	0.00	0	0.30	80	10.50	80.00	0	90.50 €
MR,										
Carcasa de retrovisor Izquierdo	Pintura	Leve	0.00	0.3	0.00	10	0.00	24.70	0	24.70 €
Paragolpes Delantero Texturado (desmontado)	Pintura	Leve	0.00	0	1.20	80	42.00	80.00	0	122.00 €
TAP	Pintura	Leve	0.00	0	0.00	45	0.00	45.00	0	45.00 €
Cubre carter	Sustituir	Sustituir	182.13	0	0.50	0	17.50	0.00	0	190.42 €
Total tasación								653.62 €		

Imágenes