

Id	1353712	M.O. Chapa	0.00
Matrícula	2644LGT	M.O. Mecánica	0.00
Bastidor	VXKUBYHYJL4194813	M.O. Pintura	0.00
Marca	OPEL	Desc. Recambios	0.00
Modelo	CORSA	Des. Material	0.00
SubModelo	1.5D 100edition	Km	12207
Color			
Cliente	OK MOBILITY ESPAÑA SLU		
Ubicación	PENDIENTE DE ASIGNAR CAMPA		
Tarifa	4 OK GROUP ES		
Nº de GFA			

Elemento	Acción	Nivel	REC	TP	TC	MP	Chapa	Pintura	Forfait	Total
Capo	Pintura	Leve	0.00	0	0.00	100	0.00	100.00	0	100.00 €
Puerta Delantero Izquierdo	Abollado	Leve	0.00	0	0.20	80	7.00	80.00	0	87.00 €
Paragolpes trasero (desmontado)	Pintura	Leve	0.00	0	0.60	80	21.00	80.00	0	101.00 €
Puerta Trasero Derecho	Pintura	Leve	0.00	0	0.00	80	0.00	80.00	0	80.00 €
MR,										
Total tasación								368.00 €		

Imágenes